

PUGET SOUND AIR POLLUTION CONTROL AGENCY

110 Union Street, Suite 500, Seattle, Washington 98101-2038

206-343-8800 / 1-800-552-3565 / Fax 206-343-7522

Registration No. 11339

Cert. Mail No. _____

No. 33290

NOTICE OF VIOLATION

Date of Violation: 6-22, 19 95 at 8:54 A.M.

Name <u>Ash Grove Cement Company</u>	Responsible Person, Title <u>Gerald Brown, Safety/Environmental Manager</u>		
Location of Violation (Address) <u>3801 E. Marginal Wy. S.</u>	City <u>Seattle</u>	Zip <u>98134</u>	County <u>KING</u>
Mailing Address <u>3801 E. Marginal Wy S.</u>	City, State <u>Seattle, WA</u>	Zip <u>98134</u>	Phone <u>623-5596</u>

DID UNLAWFULLY CAUSE OR ALLOW VIOLATION OF:

REGULATION I OF THE PUGET SOUND AIR POLLUTION CONTROL AGENCY FOR:

- ☐ Section 5.05(e) Failure to develop and implement an operation and maintenance plan.
- ☐ Section 6.03(a) Failure to obtain Notice of Construction approval prior to construction/installation/establishment of a source.
- ☐ Section 6.09(b) Failure to meet conditions of an Order of Approval.
- ☒ Section 9.03(a) Visible emissions in excess of 20% opacity for periods aggregating more than 3 minutes/hour.
- ☐ Section 9.04 Particulate matter deposited in quantities/characteristics/duration so as to be injurious or interfere with enjoyment of life/property.
- ☐ Section 9.11(a) Emission of air contaminant in quantities/characteristics/duration so as to be injurious or interfere with enjoyment of life/property.
- ☐ Section 9.12(b) Emission of odor-bearing air contaminants without use of best available control technology.
- ☐ Section 9.15(a) Emission of fugitive dust without use of best available control technology.
- ☐ Section 9.15(b) Operation of vehicle on paved public roadway with dirt/mud/debris on undercarriage (track out) or load spillage.
- ☐ Section 9.15(c) Emission of fugitive dust from manufacturing process equipment or control apparatus.
- ☐ Section 9.16 Failure to apply VOC-containing material using spray equipment in an enclosed area with filtered exhaust and vertical stack.
- ☐ Section 9.20 Failure to operate and maintain equipment in good working order.
- ☐ Section _____
- ☐ Section _____

FACTS ALLEGED TO CONSTITUTE A VIOLATION Causing or allowing blue, white smoke that was greater than 20% opacity for over 3 minutes in 1 hour from the top of the clinker cooler end of the kiln. (at shroud over cooling)

CORRECTIVE ACTION ORDER

Under the provisions of Section 3.09 of Regulation I and RCW 70.94.211 you are ordered to submit a written report within ten (10) days of receipt of this Notice describing the necessary corrective action you have taken or propose to take, including a schedule, to achieve continuous compliance with the regulations, and take the following necessary corrective action:

Issued By M. M. G. Fee

6/23/95 0945
Date/Time

Received By [Signature]
Signing this Notice is not an admission of guilt